

LAZY JACK SYSTEM FOR L-33

SPREADER

EYE OR STRAP

NOTES:

BY EXPERIENCE I HAVE DETERMINED

1. BLOCKS ARE NOT NECESSARY 3/16 LINE
2. 3/16" DACRON IS MORE THAN ADEQUATE
3. BECAUSE THE SYSTEM IS ATTACHED TO THE BOOM ONLY AT ONE POINT NO SAIL COVER MODIFICATION IS NECESSARY
4. TOTAL COST IS ABOUT \$25.00

NOTE A LOOP AND KNOT WOULD WORK JUST AS WELL BUT THE SHRINK TUBING LOOKS BETTER

